Note, for use only with existing approved suppliers

PART A: REASONABLE ASSURANCE OF SUPPLIER QUALITY PROGRAM CONTINUED EFFECTIVENESS

Vendor and Station Contact Info	illation					
Sequential Number	PPA-20-999-R0					
Revision Date	12/11/2020					
Condition/Incident Report / Doc Reference	Utility generated IR #:					
Supplier Name / Number	ABC Diesel Generator, NUPIC number 99928					
Vendor Contact /Title/Phone	John Doe General Manager, Quality Management, Special Applications +33 3 88 67 54 60 45 Email - john.doe @abc.com					
Utility Point of Contact /Phone	Phone David Doe, 999-999-9999					
Last Audit or Survey Date / No.:	Audit Exit – 7-12-2017, NUPIC # 245001					
25% Audit Grace End Date:	udit Grace End Date: Jan 28, 2021					
Other Information:	Although this is a NUPIC audit, there are only two US Utilities as users. Other Information: International users are IBE, KNP, and VAT					
Supplier Affirmation of Ongoing QA Program or Control of Critical Characteristics:	QA Program or Control of					
Additional Information Attached: Utility Over/Short/Damaged/Discrepant (OSD&D) report						
Additional Information ☐ Referen	ced: N/A					
Reason Audit or Surveillances	Can Not Be Performed at Supp	olier's Facility				
		a both of which do not allow travel from foreign In addition, the utility's travel policy does not permit				
December DDA						
Reason for PPA:	D Net socilelle	Distance at all an engatility trace ()				
☐ Critical spare part level reached	☐ Not available as received SR	☐ Inter-station or utility transfer not available ☐ Impact to station (e.g., TS 3.0.3, Refueling, SOW)				
☐ Unable to dedicate commercial☐ Other (explain below)	☑ Alternate Supplier unavailable☐ Other (explain below)	☑ Other: ABC manufactures unique components for the Utility's Emergency Diesel Generators. These components are proprietary and not available from other manufactures. Inter-utility transfers will be limited due to available inventory. Utility X is the only other US Utility that uses this manufacturer.				

Note, for use only with existing approved suppliers

Discussion of reason PPA is being used including urgency and basis for reasonable assurance of Quality:

Need: Due to lead time and specificity of parts/components, alternate means of these critical parts/components is not an option. ABC is a supplier for specific safety related emergency diesel generators and generator replacement parts, and is subject to additional scrutiny by the regulatory body.

Alternate Means of Obtaining Part: None. There are only two US users of safety related components and parts for the ABC brand diesel generator. Due to the lead time of ordering components/parts, utility transfer from the only other US user would be highly unlikely.

Supplier Quality Performance Re	eviews:
---------------------------------	---------

The following sources have been reviewed in the previous 12 months from Date: _____12/11/2020

Based on this information source, is the Supplier QA Program potentially negatively impacted? Check appropriate box:

		in this information source, is the		٠٠٠٠	or an integranii potentianij neg	u	~.,	impacted: effect appropriate som
Υ	N	N/A	Υ	N	N/A	Υ	Ν	N/A
	\boxtimes	☐ 10 CFR Part 21		\boxtimes	□ NRC Insp. Reports		\boxtimes	☐ INPO IRIS Reports
	\boxtimes	□ Vendor Improvement Plan			□ Utility CAP Reports		\boxtimes	☐ Supplier QA Location
	\boxtimes	☐ Vendor NCRs/CARs		\boxtimes	☐ Supplier QA Man. Changes		\boxtimes	☐ Significant Supplier Org Changes
		□ Receipt Inspection Reports			☐ Vendor QA Staffing Level		\boxtimes	☐ NUPIC Industry Issues (including
(lis	st re	ports reviewed and results below)	Ш		□ Veridor QA Starring Lever	оре	en fi	indings since previous audit)
ıf +b		aswar to any of the above is "VE	c" ^	r "N	I/A" place provide information	an ir		mmonts soction holows

If the answer to any of the above is "YES" or "N/A", please provide information in comments section below:

Comments:

Utility supplier issues are documented via the; therefore, the CAP process would not contain and supplier issues for ABC.

Since the audit of ABC was in the final preparation stages prior to restrictions in travel, the audit preparation was completed by Utility X. Conversations were held with the audit lead and it was confirmed that during the preparation phase of the audit, there were no NRC, INPO, Part 21 notifications, or Industry issues identified for ABC. Also, our documented history of ABC does not shown any conditional clauses ever implemented for this company.

Degree of Standardization and Complexity of Items or Services:

Describe the degree of standardization and complexity of the item or service. Include any related experience in non-nuclear industries, if applicable.

ABC is not a commodity based supplier. Scope of Supply is for unique diesel generator components and parts.

Receipt Inspection Reports Reviewed:

List receipt inspection reports reviewed from the last three years and their results. Provide an overall conclusion based on these results whether the supplier is adequately performing, or whether additional restrictions should be imposed prior to additional orders.

OSD&D:

Note, for use only with existing approved suppliers

• Enhanced receiving inspections beyond visual inspections and quality checks. Based on safety-significance and

Mitigating Actions Based on Review of Supplier Performance and QA Program Compliance:

If concerns are identified based on the above "Part A" evaluation, the following mitigating actions may be considered:

•	complexity of item, consider use of remote source verification as approved in ML20181A445.
	N/A
• 1	dentification of any additional requirements/restrictions to be placed on the supplier:
	N/A
ummarı	//Conclusion, including basis for reasonable assurance of Quality:
ullillary	//Conclusion, including basis for reasonable assurance of Quality.
Determi	nation of Interim Supplier Status:
⊠ Rea	sonable Assurance of Quality
	ginally Effective Evidence of Quality
□ Not	approved for interim consideration
been de	Based upon review of ABC quality program, historical Supply issues, Regulatory and Industry issues, it has termined that the extension of ABC for purchase of safety related diesel engine replacement components and warranted for an additional 6 months or performance of the audit, which-ever comes first.

Action Tracking Items Required for Closure and Interim Actions:
Action Tracking items Required for Closure and Interim Actions:
This temporary ASL Reinstatement will expire? ⊠ Yes □ No
Expiration Date: February 1, 2022
Interim review required? ⊠ Yes □ No
Review periodicity: 6 months (Action Tracking Item)
Other actions: None

Note, for use only with existing approved suppliers

Evaluation stops here if supplier QA program can be determined with reasonable assurance to be sufficiently effective with mitigating actions to allow new items or services to be utilized on an interim basis.

End of PART A

PART B: REVIEW OF IMPACT ON SPECIFIC PLANT APPLICATION FOR PART INSTALLATION

Should the evaluation conclude the QA program is marginally effective and there is a specific item or service needed to support plant operation and the ability to audit is not possible, continue the evaluation below to document reasonable assurance for specific items and services needed. The below evaluation should support/follow the conditional release or nonconformance disposition process.

Part Information	
Vendor Part Serial Number	
Vendor Part Number	
Vendor Part Description	
Station Identification Number	
Station Part Description	
End Use Application:	
Safety Related SSC Impacted:	
ASME Code Pressure Boundary	
Other Code/Standards	
Engineering Contact	
Classification:	☐ Safety-Related ☐ Non-Safety Related ☐ 50.69 RISC-3 (NEI 17-05)
Additional i	nformation ☐ Attached / ☐ Referenced: Tech Eval 2892888-03
Design Bases Function of Part:	
Doorgin Ducoco i unionom or i union	
Potential Failure Mechanisms:	
otential Fanare Meenanisms.	

Note, for use only with existing approved suppliers

Operability Determination:
For stations who have not implemented NEI 18-03: Component: 2A Emergency Diesel Generator Tech Spec: 3.5.2(a) □ Operable □ Operable but Non-Conforming □ Operable but Non-Conforming with compensatory measures □ Operable per 50.69 RISC-3 Evaluation □ Inoperable In addition, the second snubber on this support was tested during the last refueling outage and passed both the drag and functional test with no issues. It will be tested again this outage as a contingency action.
Risk Assessment (not required where reasonable assurance of operability exists):
Is failure of component or piece part modeled in the station PRA? \square Yes \square No
Change in CDF: N/A
Compensatory Actions Required based on change in CDF? \square Yes \square No
Change in CDF with compensatory actions: N/A
Would failure of this component impact defense in depth? \square Yes \square No \square N/A
Discussion:
Would failure of this component result in reduction in safety margin? ☐ Yes ☐ No ☐ N/A
Discussion: No safety margins associated with this function.
Any other licensing / design bases issues associated with failure of this component? \square Yes \square No
Discussion: No special DB or LB considerations.
Compensatory Measures (only required if CDF change greater than 1.0 E-07 unmitigated):
1.

Note, for use only with existing approved suppliers

Close out:
This temporary ASL Reinstatement will expire? ☐ Yes ☐ No
Expiration Date:
Interim review required? ☐ Yes ☐ No
Review periodicity:

This form alone is not a stand-alone quality record. It is a quality record when attached to a quality document. Similar forms meeting the intent may be used.